



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
BURLINGTON ROAD	opp 50	Damaging	Kerbs missing, unable to adequately repair without tree damage/removal	Malus sp	Plant in new pit opp 50, (same position as felled tree)	Crataegus laevigata 'Paul's Sc
BURLINGTON ROAD	O/S 33	Damaging	F/W mounded and stem base wounded	Prunus serrula	Plant in existing pit o/s 33, (same position as felled tree)	Crataegus laevigata 'Paul's Sc
BURLINGTON ROAD	O/S 21	Damaging	F/W mounded and uplifted and stem bark necrosis	Prunus serrula	Plant in existing pit o/s 21, (same position as felled tree)	Crataegus laevigata 'Paul's Sc
BURLINGTON ROAD	O/S 18	Dangerous	Stem base decayed	Crataegus sp	Plant in existing pit o/s 18, (same position as felled tree)	Crataegus laevigata 'Paul's Sc
BURLINGTON ROAD	O/S 40	Damaging	F/W uplifted and cracked	Prunus serrula	Plant in existing pit o/s 40, (same position as felled tree)	Crataegus laevigata 'Paul's Sc
BURLINGTON ROAD	O/S 42	Damaging	F/W uplifted and cracked	Prunus serrula	Plant in existing pit o/s 42, (same position as felled tree)	Not Known